

**Table 3-1**  
**Summary of Residential Well Survey**  
**RI/FS Work Plan**  
**Gibbsboro, Camden County, New Jersey**

ADDRESS	FORM OF CONTACT	ANSWER	COMMENT
9 Marlton Ave.	Sent letter	No response to date	Visited house 1/31/97. Could not obtain interview
19 Marlton Ave.	Sent letter	No response to date	Visited house 1/31/97. Could not obtain interview
13A. Marlton Ave.	Sent letter	No response to date	Phone unlisted. Could not obtain interview
13b Marlton Ave.	Sent letter/phone interview	NJ American Water Company	
15 Marlton Ave.	Returned form	Well	Well depth 173 ft; 240gpd
19 Marlton Ave.	Returned form	NJ American Water Company	
49 Marlton Ave.	Returned form	NJ American Water Company	
9 United States Ave.	Letter/phone call	NJ American Water Company	Originally listed as "90 United States Avenue". No such address exists. Corrected based on tenant name.
10 United States Ave.	Sent Letter	No response to date	Unlisted. Could not obtain interview
11 United States Ave.	Returned form	NJ American Water Company	
14 United States Ave.	Returned form	NJ American Water Company	
15 United States Ave.	Sent letter/phone interview	NJ American Water Company	A well was abandoned approximately 60 years ago
18 United States Ave.	Returned form	NJ American Water Company	A 19th century dug well is on the property but not in use.
20 United States Ave.	Returned form	NJ American Water Company	Well has been abandoned
25 United States Ave.	Phone call	well	Well depth ~250ft; 300 gpd
41 Berlin Rd	Sent letter/phone interview	NJ American Water Company	"Have not used well water in years"
44 Berlin Rd	Sent letter	No response to date	No phone listed. Could not obtain interview
44 Berlin Rd	Returned form	South Jersey Water Company	It is assumed that the purveyor is NJ American Water Co.
45 Berlin Rd	Sent letter/phone interview	NJ American Water Company	
49 Berlin Rd	Sent letter/phone interview	NJ American Water Company	
171 Gibbsboro Road	Not part of the Paint Works door-to-door Survey	Not known. NJDEP records indicate well on property.	Total depth of domestic well 85 ft., screened interval at 60 ft., static water level at 10 ft. Well installed 8/26/52.
18 Haddonfield-Berlin Road	Not part of the Paint Works door-to-door Survey	Not known. NJDEP records indicate well on property.	Total depth of domestic well 235 ft., screened interval at 235 ft., static water level at 30 ft. Well installed 2/10/56.

**Table 3-1 (Continued)**

ADDRESS	FORM OF CONTACT	ANSWER	COMMENT
40 Johnson Drive	Not part of the Paint Works door-to-door Survey	Not known. NJDEP records indicate well on property.	Total depth of domestic well 155 ft., screened interval at 155 ft., static water level at 145-155 ft.. Well installed 9/19/84.
44 Johnson Drive	Not part of the Paint Works door-to-door Survey	Not known. NJDEP records indicate well on property.	Total depth of domestic well 151 ft., screened interval at 151 ft., static water level: none. Well installed 4/1/82.
Rt. 561 (based on Permit description) (owner: Army Corps of Engineers located at 207 E. Stanton Rd., Wildwood Crest, NJ)	Not part of the Paint Works door-to-door Survey	Not known. NJDEP records indicate well on property.	Well located based on NJDEP permit coordinates. Total depth of domestic well 415 ft., screened interval at 260-290 ft., static water level at 118 ft, installed 4/8/59. Well log available.
Voorhees	Not part of the Paint Works door-to-door Survey	Not known. NJDEP records indicate well on property.	Well located based on NJDEP permit coordinates. Total depth of domestic well 234 ft., screened interval: none, static water level at 80 ft. Well installed 4/18/55
Resident - Gibbsboro-Clementon Road (north of Rt. 561)	Not part of the Paint Works door-to-door Survey	Not known. NJDEP records indicate well on property.	Well located based on NJDEP permit coordinates. Total depth of domestic well 100 ft., screened interval at 100 ft., static water level at 30 ft. Well installed 8/15/55.
10 Foster Avenue	Not part of the Paint Works door-to-door Survey	Not known. NJDEP records indicate well on property.	NJDEP well permit coordinates do not agree with owner's address. Current owner (Brandywine Realty Trust) has no knowledge of a well at this location.
101 McIntire Drive	Identified during Removal Action under USEPA oversight (2000)	Well in use	Sampled and analyzed by Sherwin-Williams during Removal Action.
3 Kresson Rd	Identified by NJDEP (1994)	Well	Sampled and analyzed by NJDEP.

Notes:

- (1) Information collected as part of the investigations conducted at the Paintworks, under NJDEP oversight
- (2) A person who would not disclose their identity, or relation to the listed resident provided the information.
- (3) Information from: Appendix A (Well Search Data) of SWC's February 2001 RI Report for the Paint Works Corporate Center developed based on a 1993 search of the NJDEP Bureau of Water Allocation well records.
- (4) Information collected from miscellaneous investigations as noted.